


STATE North Carolina	COUNTY Gates	TOWN OR VICINITY Buckland
INDEX NUMBER VC, 37-BUCLA, 1	MONUMENT ✓ Smith House (Buckland) NC, Rd 37	
REPRESENTED IN NEGATIVE FILE	H.A.B.S. SURVEY NO. NC-73	Period: late 18th century
PUBLISHED PHOTOGRAPHS	Present condition: poor; woodwork of interior removed	
PUBLISHED DRAWINGS	Description: Frame; two stories; two rooms deep; pairs of outside end chimneys brick, Flemish bond; gable roof. Front five bays center door; lower sash 9/9, upper 6/9; modil lioned cornice. Plan central hall, two rooms either side. In the yard are a group of early out-  buildings, including a	
670 6-8369	HISTORIC AMERICAN BUILDINGS SURVEY	

 2p  
 1d

✓

dairy. This is square in plan, frame, with a wide grille of scrolled slats at cornice line. Cornice a large plastered cove with wood crown mould. Roof hipped and shingled.

Prepared by Thomas T. Waterman 1940